




U.S. DEPARTMENT OF INTERIOR
U.S. GEOLOGICAL SURVEY

Prepared in cooperation with the
PUERTO RICO ELECTRIC POWER AUTHORITY

WATER-RESOURCES INVESTIGATIONS REPORT 03-4102

Lago de Matrullas, Puerto Rico, Bathymetry, December 2001 - PLATE 1
Soler López, L.R., 2003, Sedimentation Survey
of Lago de Matrullas, Puerto Rico, December 2001

66°28'30"



18°13'00"


66°29'00"

18°12'30"

18°12'00"

Shoreline modified from the U.S. Geological Survey Quadrangle
Orocovis, Puerto Rico, 1957, photorevised in 1982.
Lambert conformal conic projection.
Puerto Rico state plane coordinate system. (Puerto Rico datum, 1940 adjustment)

LAGO DE MATRULLAS, PUERTO RICO
BATHYMETRY, DECEMBER 2001
by Luis R. Soler-López
2003



Shoreline modified from the U.S. Geological Survey Quadrangle Orocovis, Puerto Rico, 1957, photorevised in 1982. Lambert conformal conic projection. Puerto Rico state plane coordinate system. (Puerto Rico datum, 1940 adjustment)